

[Next Unread Message](#)**View Message**

---

**Sent on** 06 19 2014 **Expires on** 07 03 2014  
**From** Parts and Service Division  
**Subject** Request for Info: 2013-2014 Odyssey, Pilot & Ridgeline Steering Wheel Vibration

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**RE:** Request for Info: 2013-2014 Odyssey, Pilot & Ridgeline Steering Wheel Vibration

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2013-2014 Odysseys, Pilots & Ridgelines with a complaint of steering wheel vibration due to wheel/tire imbalance. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the issue.
2. Mileage must be less than 10,000 miles.
3. No previous wheel balance repair.
4. All 4 tires must be original OEM tires.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.