



## Roadster Radio Station Display in Cluster Disappears After a Few days

[Printable Version](#)

Rate This Article

(Average Rating: No Rating)

[Version 1](#)

**Language** | English

[Show Properties](#)

### Summary:

It has been brought to BRP's attention that in some cases the radio station display option in the cluster will revert to "no display" after a few days.

### Type:

General


### TST Detail:

BRP is looking into the situation. This issue has been identified as a software problem between the cluster and the radio module.

At this time replacement of parts is not the solution since they all have the problem.

BRP is working on identifying a solution.

This is how the setting is to display the radio station in the cluster main screen



Radio station is displayed under the speed.