

DanyD
BRP Service Dept - N/A



Posts: 637
Registered: 10-19-2011
Location: NA

✓ **Water pump mechanical seal investigation - 420220413 - On 2012 units** [Edited]

Options ▾

10-08-2012 09:43 PM - edited 10-15-2012 01:25 PM

It has come to BRP's attention that water pump mechanical seal failures have risen in recent weeks. In the event you have a Spyder with a leak from the weep hole (oil or coolant) we would like to have more information from you.

1. How much is leaking? A picture would help. Was there enough to drop on the floor?
2. Does the leak happen more when the unit engine is cool or hot?
3. A B.U.D.S. report would help to understand the unit's engine use by the RPM profile.
4. To your knowledge is the the unit's 1st failure or a reoccurring failure?

Please communicate these details to service@brp.com to the attention of the Spyder team along with the unit's VIN and mileage. We will RPQ it in order to advance in the investigation.

Dany D
Roadster Product Specialist

Solved! Go to Solution.

Me too

[Report Inappropriate Content](#)
Message 1 of 22 (639 Views)

Everyone's Tags: [bomba de agua](#) [Fuga bomba de agua](#) [wasserpumpe](#)
[View All \(3\)](#)

0 Kudos + [★](#) [Reply](#)

[Add Tag...](#)