

EVAP System Leak from the Filler Neck? *Don't* Replace the Fuel Fill Pipe!

AFFECTED VEHICLES

2016 Pilot and 2017 Ridgeline

EDITOR'S NOTE: This article replaces the one posted in **June 2017** to extend the article's shelf life. The issue(s) covered are still being addressed.

If there's an EVAP system leak from the filler neck (DTC P0455 [EVAP system large leak detected] or P0456 [EVAP system very small leak detected] is set), **don't** replace the fuel fill pipe! Instead, replace the mis-fuel inhibit device and the main flap unit. Honda parts stock carries replacement parts just for this purpose.

For replacement procedures, refer to the service information. And for a look at this replacement in action, be sure to check out the *Tech2Tech*[®] video "Replacing the Filler Neck Main Flap Unit."