

Reference:

ITB16-015b

Date:

February 27, 2018

VOLUNTARY SERVICE CAMPAIGN 2011 – 2013 QX56 AND M56; TIMING CHAIN

CAMPAIGN ID #: P6305 (inactive)
APPLIED VEHICLES: 2011-2013 QX56 (Z62)
2011-2013 M56 (Y51)

Service Campaign ID # P6305 is No Longer Active.

- Infiniti Service Campaign Bulletin ITB16-015 for Service Campaign P6305 was originally issued on May 5, 2016.
- Service Campaign ID # P6305 is no longer active.
- Repair orders opened after February 27, 2018 are no longer eligible for reimbursement under Campaign ID #P6305.
- Please discard previous versions of ITB16-015.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.