

| | |
|----------------------|--|
| Reference | SSM73384 |
| Models | F-PACE / X761 F-TYPE / X152 XE / X760 XF / X250 XF / X260 XJ / X351 |
| Title | Rear Differential Pinion Seal Oil Leak |
| Category | Driveline |
| Last modified | 07-Jun-2017 00:00:00 |
| Symptom | 509000 Axle Concerns |

Content **Issue:**
Rear differential oil leak evident from the pinion seal.

Cause:
Parts/Supplier quality.

Action:
Please only submit EPQR's for vehicles post the VIN range below or any repeat repairs:

XF (X250) - U88785 - All Engine Variants
XJ (X351) - W05647 - All Engine Variants
F-Type (X152) - K45470 - All Engine Variants
F-Pace (X761) - A490582 - 3.0S/C/AJ126
XE (X760) - A973645 - 3.0S/C/AJ126
XE (X760) - P07239 - 3.0S/C/AJ126
XF (X260) - Y46373 - 3.0S/C/AJ126 and 3.0 TDV6

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.