

Safety Recall and Service Campaign - Technician Certification Requirements

Posted 1/9/2018

IMPORTANT:

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right.

Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

| Safety Recall or Service | | | | | Ce | rtificat | | | | | | | | | |
|--------------------------------------|---|----------|-------------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|---------|---|
| Campaign | Description | Maint | | Cert | ified | | | | Expert | t | | Mast | MDT | Special | Additional Requirements |
| Campaign | | want | EG | DT | СН | EL | EG | DT | СН | EL | HY | IVIASL | IVIDI | Courses | |
| Safety Recall HOR | Certain 2012-2015 Prius PHV Electric Vehicle Fuse Fracture | | | | | | | | | | ✓ | ✓ | ✓ | | |
| Safety (Noncompliance) Recall | Certain 2017 Sienna and Tacoma, 2017-2018 4Runner and Tundra, 2018 Highlander and Rav4 Load Carrying Capacity Modification | | ✓ | √ | ✓ | ✓ | ✓ | ✓ | √ | ✓ | ✓ | √ | √ | | |
| H0Z | Label | | | | <u> </u> | | | | | | | | | | |
| SSC HOY | Certain 2018 Tundra and Sequoia Center Air Bag Software Update | | > | > | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall H0V | 2005-2007 and 2009-2010 Sienna Shift Lock Solenoid Assembly | | ~ | ✓ | ~ | ~ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety (Noncompliance) Recall HOW | Certain 2018 C-HR Electronic Parking Brake Reflash | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC H0T | Certain 2018 Camry Rear Wheel Arch Sealer Gap | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall H0U | Certain 2016 Prius Inverter Assembly Replacement | | | | | | | | | | ✓ | ✓ | ✓ | | |
| SSC HOP | Certain 2017 Yaris Instrument Panel Wire Harness | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC HON | Certain 2018 C-HR Rear Bumper Garnish | ✓ | ✓ | √ | ~ | ~ | ✓ | ~ | ✓ | ~ | ✓ | ✓ | ✓ | SC17A | All technicians in staffmaster are eligible to perform this repair with the completion of SC17A |
| LSC HOJ | Certain 2007-2014 FJ Cruiser Fuel Tank | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC H0L | Certain 2018 C-HR Parking Brake Cover | ✓ | √ | √ | ~ | ~ | ✓ | ~ | ~ | ~ | ~ | √ | ✓ | SC17A | All technicians in staffmaster are eligible to perform this repair with the completion of SC17A |
| Safety Recall HOS | Certain 2008-2016 Landcruiser Driver Airbag Assembly | | | | | | | | | ✓ | | ✓ | ✓ | | |
| LSC H0F | Certain 2005-2010 Tacoma, 2005-2008 Sequoia, and 2007-2008 Tundra CRC Application | ✓ | ✓ | ✓ | ~ | ✓ | ✓ | √ | ✓ | √ | √ | √ | ✓ | SC17A | All technicians in staffmaster are eligible to perform this repair with the completion of SC17A |
| Safety Recall H0H | Certain 2016-2017 Tacoma Crankshaft Position Sensor | | ✓ | | | | ✓ | | | | | ✓ | ✓ | | |
| Safety Recall H0M | Certain 2016 Camry and 2016 Avalon CV Axles | | | ✓ | | | | ✓ | | | | ✓ | ✓ | | |
| Safety Recall G04 | Certain 2011-2016 Sienna Power Sliding Door | | | | | ✓ | | | | ✓ | | ✓ | ✓ | SRG04 | SRG04 Instructor Led course from the Region |
| Safety Recall H0K | Certain 2016 Tundra Knee Airbag Bolts | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Emission Noncompliance Recall HOI | Certain 2018 C-HR Emission Label Installation | | ✓ | ✓ | ✓ | ~ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall H0G | Certain 2016-2017 Tacoma Rear Differential Leak | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall HOC | Certain 2016-2017 Tundra Bumper Reinforcement Brackets | | ✓ | ✓ | ✓ | ✓ | \ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| SSC H0E | Certain 2016 -2017 MY Mirai Fuel Cell System Updates | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| SSC H0D | Certain 2016 Scion iA & 2017 Toyota Yaris iA Certification Label | | √ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| SSC G0Y | Certain 2006-2008 MY RAV4 Muffler Inspection | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| LSC G0X | Certain 2016 MY RAV4 & RAV4 HV Power Rear Hatch ECU | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | Expires November 30, 2019 |

| | | | | | Ce | rtificat | ion Le | vel Re | quirem | ents | | | | | |
|-----------------------------------|---|-------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------------|---|
| Safety Recall or Service | Description | | | Cert | ified | | | | Expert | | | | | Special | Additional Requirements |
| Campaign | | Maint | EG | DT | СН | EL | EG | DT | СН | EL | HY | Mast | MDT | Courses | |
| 0.5 | Certain 2016 Avalon and Certain 2017 Camry | | | | | | | | | , | | | √ | | |
| Safety Recall G05 | Incorrect Passenger Knee Airbag Fasteners | | | | | | | | | • | | v | • | | |
| LSC G02 | Certain 2015-2016 Camry DSS ECU Update | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | Expires October 31, 2019 |
| SSC GOZ | Certain 2017 MY Sienna Powertrain ECU Software Update | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall GOC | Certain 2003-2006 MY Land Cruiser, 2005-2006 MY Sequoia, 2005- | | | | | | | | | 1 | | 1 | ✓ | | |
| - | 2006 MY Tundra, 2004-2006 MY 4Runner SRS ECU | | | | | | | | | Ť | | · | | | |
| Safety Recall G0W | Certain 2016 MY Prius Front Passenger Airbag | | | | | | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall G01 | Certain 2016 - 2017 MY Prius Parking Brake Cable Clip | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | SC17A | All technicians in staffmaster are eligible to perform this repair with the completion of SC17A |
| Safety (Noncompliance) Recall G03 | 2016 MY Highlander Brake Fluid Reservoir Sensor Connector | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0P/G0R/H0A | Certain 2006-2011 MY Yaris Hatchback & 2007-2012 MY Yaris Sedan, 2009-2013 Corolla, 2009-2013 MY Matrix, 2008-2013 MY Scion xB, 2010-2013 4Runner, and 2011-2013 Sienna Takata Airbag | | | | | | | | | ✓ | | ✓ | ~ | | |
| Safety Recall FOS | 2009-2012 MY RAV 4 & 2012-2014 MY Rav4 EV Ft. Wiper Arm Crank Arm | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0U | 2010 - 2012 MY Prius & Prius Plug-in Curtain Shield Airbag | | | | | | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall GOS | 2015 MY Yaris Front Strut Bearing Inspection | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall G0V | 2006-2011 MY RAV4 Rear Lower Suspension Arm No.1 | | | | | | | | √ | | | ✓ | ✓ | SCGOV SCGOVH | Technicians must also successfully complete SCGOV online and SCGOVH conducted by the Regions. |
| LSC G0T | Certain 2016 MY Prius Simple Advance Parking Guidance System | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0M | 2015-2016 MY Toyota Prius V Emission Control Information Label | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC GOL | 2016 MY Scion iA Spare Tire Pressure Adjustment | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC G0K | 2016 MY Scion iA Inspection and Adjustment of Coolant Concentration | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0J | Certain 2016 MY Avalon, Avalon HV & Camry Occupant Classification System (OCS) | | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0I | Certain 2016 MY RAV4 Brake Actuator Inspection/Replacement | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall G0H | Certain 2016 MY Sienna Front Driver and Passenger Seat Belt Height Adjuster Replacement | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0G | 2015-2016 MY Toyota Sienna Oxygen Sensor Replacement | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0F | 2006-2012 MY Rav4, 2012-2014 Rav4 EV Rear Outboard Seatbelts | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall G0E | Certain Model 2013 - 2016 MY Scion FR-S Ignition Key Interlock System (Automatic Transmission Models with Ignition Key ONLY) | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | √ | ✓ | ✓ | ✓ | √ | | |
| Safety Recall F0V | Certain 2013-2015 MY Avalon, Avalon HV Pre-Collision System | | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | SCF0V | |
| SSC FOU | Certain 2010 - 2014 MY Tacoma 2TR-FE Vehicles Exhaust Pipe Replacement for Catalytic Converter | | ✓ | √ | ~ | √ | ✓ | ✓ | √ | ✓ | ✓ | ✓ | ~ | | *If inspection determines the vehicle requires additional electrical repairs, it must be preformed by a technician who is expert or above |
| Safety Recall F0T | 2016 MY Tacoma Driver Knee Airbag Module Bolts | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall FOR | 2012-2014 MY Prius V Software Update for Motor Generator ECU and Power Management ECU | | | | | | | | | | ✓ | ✓ | ✓ | | |

| | Т | | | | Ce | rtificat | ion Le | vel Re | auiren | ents | | | | | |
|---|--|-------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|---------|--|
| Safety Recall or Service Campaign | Description | | | Cert | tified | | | | Exper | | | | | Special | Additional Requirements |
| | · | Maint | EG | DT | СН | EL | EG | DT | CH | EL | HY | Mast | MDT | Courses | · |
| Safety Recall FOP | 2007 MY Highlander Hybrid Engineer Software Update for Air Fuel (A/F) Sensor Monitoring | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC FON | 2014 MY Corolla Eco (2ZR-FAE) ECM Software Update for Variable Valve Lift Control | | ✓ | √ | 1 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC FOM | 2011 MY Sienna 3rd Row Seat Back Panel Replacement | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall FOL | 2004-2005 MY RAV4 Front Driver Airbag Inflator Module | | | | | | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall FOK | 2015 MY Scion tC Vehicles Rear Suspension Arm | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall F0J | 2014-2015 Model Year RAV4, 2015 Highlander and Highlander HV, and 2015 Camry and Camry HV Vehicles | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall F0I | 2012 - 2014 MY RAV4 Electric (EV) EV Traction Motor Assembly | | | | | | | | | | ✓ | ✓ | ✓ | 012D | |
| Safety Recall F0H | 2012 - 2015 MY Yaris Hatchback Headliner Replacement | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall FOG | TRD Accessory Wheels and Light Truck Tires Tire and Loading Information Label | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall F0F | 2015 Model Year Yaris Rear Axle Hub Bearing Torque Confirmation | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall F0E | Certain 2014 Model Year FJ Cruiser Vehicles Steering Intermediate Shaft Assembly | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall F0D | Certain 2011-2012 Model Year Avalon Vehicles Premium Audio System - Rear Sub-Woofer | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety (Noncompliance) Recall FOC | Certain 2014 and Early 2015 Model Year Prius V Vehicles Occupant Classification System (OCS) Sensor | | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC FOB | Certain 2012-2014 Model Year Tundra and Sequoia Vehicles | | | | | | | | | ✓ | | ✓ | ✓ | | |
| LSC FOA | Certain 2012-2014 Model Year Tundra and Sequoia Vehicles ECM Software Update | | √ | 1 | ✓ | ~ | ✓ | ✓ | √ | ✓ | √ | ✓ | ✓ | | |
| Safety Recall E07 | Certain 2015 MY Sienna Vehicles Second Row Overhead Assist Grips | | | | | | ✓ | ✓ | ✓ | √ | ✓ | ✓ | ✓ | | |
| Safety Recall E05 | Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall E04 – High Absolute Humidity | Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Passenger Airbag Inflator Module | | | | | | | | | ✓ | | ✓ | ✓ | SC13B | |
| LSC E03 | Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update | | √ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall E02 | Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement | | | | ~ | | | | √ | | | ✓ | √ | | Remedy launched for vehicles in Boston, New York, CAT, Cincinnati, Denver, Portland and Chicago regions. |
| Safety Recall E01 | Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak | | √ | ✓ | ~ | ✓ | √ | ✓ | ~ | ~ | ✓ | ✓ | ~ | | |
| Safety Recall EOZ | Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag | | | | | | ✓ | √ | ✓ | ✓ | √ | ✓ | ✓ | | |
| Safety (Noncompliance) Recall E0Y | Certain 2014 MY FJ Cruiser Trail Teams Ultimate Edition Package Lower Ball Joint Bolt | | | | √ | | | | ✓ | | | ✓ | ✓ | | |
| EOX | Certain 2008-2014 MY Tacoma and FJ Cruiser TRD Accessory Wheels and Toyota Recommended LT Tires | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety (Noncompliance) Recall EOW | Certain 2014 Model Year Sienna Vehicles Transmission Shift Control Cable | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | - |

| 0.6.1 | | | | | Ce | rtificat | ion Le | vel Re | quirem | ents | | | | | Additional Requirements |
|---------------------------------------|---|-------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|---------|--|
| Safety Recall or Service Campaign | Description | Maint | | Cert | ified | | | | Expert | | | Mast | MDT | Special | |
| Campaign | | Wante | EG | DT | CH | EL | EG | DT | СН | EL | HY | Widst | IVIDI | Courses | |
| LSC EOU | 2007-2011 MY Camry Hybrid Vehicles Brake Reservoir Tank Replacement | | | | | | | | ✓ | | | ✓ | ✓ | | |
| Safety Recall EOT | Certain 2014 Model Year Highlander and Highlander HV Passenger Seatbelt Selectable Force Limiter – Software Update | | | | | | ✓ | ✓ | ✓ | ~ | ✓ | ✓ | ✓ | | |
| Special Service Campaign ESS | Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall EOS | Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable | | ✓ | ✓ | ~ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall EOR | 2014 Model Year Highlander Vehicles 2nd Row Passenger-Side Inboard Seat Track for 60/40 Split Seat | | ~ | ✓ | ✓ | ✓ | ~ | ✓ | √ | ✓ | ✓ | ✓ | ✓ | | |
| LSC EOP | Certain 2014 Model Year Toyota Highlander Hybrid Vehicles Coolant Hose Clearance | | | | | | | | | | ✓ | ✓ | ✓ | | |
| LSC EON | Certain 2011-2014 Model Year Toyota Sienna Pre-Collision System (PCS) Driving Support ECU | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall EOM | 09-10 Corolla, 09-10 Matrix, 08-10 Highlander, 09-10 Tacoma, 06-10 Rav4, 06-10 Yaris; Spiral Cable | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall EOL | 06-10 Yaris HB, 07-10 Yaris Sedan, and 08-10 Scion xD; Driver's Seat Track Assembly & Passenger Track Assembly (3-Door Yaris Only) | | ✓ | ✓ | ~ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC EOK | 2014 MY Avalon, Avalon Hybrid, Highlander, and Sienna Vehicles Safety Connect System Disabled | | ✓ | √ | ~ | \ | ✓ | ✓ | √ | ~ | ✓ | √ | ✓ | | |
| LSC EOJ | Certain 2013-2014 Model Year Avalon & Avalon HV Driver & Passenger Front Seatback Board | | ✓ | √ | ~ | ✓ | ✓ | √ | √ | ~ | √ | ✓ | √ | | |
| Safety (Non-Compliance) Recall EOH | 2013 MY Highlander 2nd Row Left Hand Seat Inboard Seat Track | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall E0G | 2003-2004 Avalon Supplemental Restraint System (SRS) Electronic Control Module | | | | | | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall E0F | 2012-2013 MY Tacoma, 2012 RAV4 Brake Actuator Reprogramming | | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety Recall E0E | 2010-2014 Prius Software Update for Motor Generator ECU & Power Management ECU | | | | | | | | | | ✓ | ✓ | ✓ | | |
| Safety (Non-Compliance) Recall EOC | 2014 MY Highlander; 3rd Row Center Seat Belt | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| Safety (Non-Compliance) Recall EOB | Multiple 2013-2014 MY Models Seat Heater Assemblies | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall DSF | 03-04 MY Corolla, Matrix, & Tundra and 02-Early 04 MY Sequoia Front Passenger Airbag Inflator Module | | | | | | | | | ~ | | ✓ | ✓ | SC13B | |
| Satety Recall DSB | 2003-2004 Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM) | | | | | | | | | ✓ | | ✓ | √ | | * Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting |
| Safety Recall D0U | 2013-2014 MY Tacoma 4 Cylinder Valve Spring Replacement | | | | | | ✓ | ✓ | | | | ✓ | ✓ | | |

| | 1 | I | | | Ce | rtificat | ion Le | vel Re | quirem | ents | | | | | Additional Requirements |
|---------------------------------------|---|---------|----------|----------|----------|----------|----------|-------------|----------|----------|----------|----------|----------|---------|--|
| Safety Recall or Service | Description | Maint | | Cert | ified | | | | Expert | | | Mant | MDT | Special | |
| Campaign | • | iviaint | EG | DT | СН | EL | EG | DT | CH | EL | HY | Mast | MDT | Courses | · |
| Safety Recall D0T | 2012-2013 Avalon, Camry, Camry HV, and Venza, 2013 Avalon HV HVAC Assembly | | | | | | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall D0S | 2013 Avalon & Avalon HV, 2013-2014 Camry & Camry HV, 2014 Corolla Windshield Wiper Switch | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall DOR | 2004-2005 and 2007-2009 Sienna Shift Lock Solenoid Assembly | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | |
| LSC DON | 2011-2012 HV Highlander HV Rear Driveshaft Assembly Replacement | | | | | | | √ ** | | | ✓ | ✓ | ✓ | 71 | **Drivetrain Expert and completion of course 071 Toyota Hybrid System |
| Safety Recall DOM | 2006-2010 MY Highlander HV Intelligent Power Module (IPM) Replacement | | | | | | | | | | ✓ | ✓ | ✓ | | |
| Safety Recall DOL | 2005-2011 MY Tacoma Access Cab Vehicles Driver and Front Passenger Seat Belt Assemblies | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall D0K | 2012 Yaris MY Power Steering Control Module | | | | | ✓ | | | | ✓ | | ✓ | ✓ | | |
| Safety Recall D0H | Safety Recall D0H: 2010 Prius; Brake Booster Pump Assembly (Accumulator) | | | | ✓ | | | | ✓ | | | ✓ | ✓ | | |
| Safety (Non-Compliance) Recall DOG | 2007-2013 FJ Cruiser Genuine Toyota Auxiliary Light Kit Accessory | | | | | | | | | | | | | | * Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting |
| Safety Recall D0F | 2003-2004 Corolla, Matrix, Tundra and 2002-2004 Sequoia Front Passenger Airbag Inflator Module | | | | | | | | | ✓ | | ✓ | ✓ | SC13B | |
| Safety Recall DOC | 2007 - 2013 MY FJ Cruiser Access Door Inner Panel | | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | √ | | * Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting |
| Safety Recall DOB | 2003-2004 MY Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM) | | | | | | | | | ~ | | ✓ | ~ | | * Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting |
| Safety Recall COM | Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007- 2009 Camry, 2007-2009 Camry HV, 2008-2009 Scion xD, 2008-2009 xB, 2008-2009 Sequoia, 2008 Highlander and Highlander HV, 2009 | | ✓ | √ | ✓ | ✓ | ✓ | √ | √ | √ | √ | ✓ | √ | SCC0M2 | |
| LSC 90K | Multiple Models and Model Years 2GR-FE (V6) Engine VVTi Oil Hose | | ✓ | | | | ✓ | | | | | ✓ | ✓ | | |
| Warranty Enhancement Program ZF5 | Certain 2012 – 2014 Model Year Prius V Extension of Warranty Coverage to the Intelligent Power Module (IPM) | | | | | | | | | | ✓ | ✓ | √ | | |
| Warranty Enhancement Program ZF3 | Certain 2010-2012 Prius, 2012 Prius V, 2010-2012 Prius Plug-In Sticking Exhaust Gas Recirculation (EGR) Valve | | ✓ | | | | ✓ | | | | | ✓ | ✓ | | |
| Warranty Enhancement Program ZE3 | Certain 2010 – 2014 Model Year Prius Vehicles Extension of Warranty Coverage to the Intelligent Power Module (IPM) | | | | | | | | | | ✓ | ✓ | ✓ | | |