

Subject MY17-18 Tacoma Bed Gap Measurement Method (RR Bumper x Bed & Bed x Cab)		Market USA
Service Category Vehicle Exterior	Section Exterior Panels/Trim	
Applicability MY17-18 Tacoma MY Tacoma		

APPLICABLE VEHICLES

2017-2018	Tacoma
-----------	--------


CONDITION

Some customers may complain that the gap between the bed and rear bumper or bed and cab is too large or uneven from left to right. This Tech-Tip is to request measurement data when reporting gap complaints.


RECOMMENDATIONS

If customer complains of the gap between the bed and rear bumper or bed and cab being too large or uneven from left to right, please submit a report with the following measurement data:

1. Bed x Bumper Gap – Measure on the outside of vehicle at middle of bumper (both sides).



2. Cab x Bed Gap – Measure on outside of vehicle 225mm down from top of bed (both sides).



LINK REFERENCES

This Tech Tip does not contain any link references

Subject

**MY17-18 Tacoma Bed Gap Measurement Method (RR
Bumper x Bed & Bed x Cab)**

Market

USA

Applicability