



**Safety Recall and Service Campaign - Technician Certification Requirements**

Posted 3/30/2017

**IMPORTANT:**

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign.

Special Courses and Additional Requirements are noted in the two columns on the far right.

Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

| Safety Recall or Service Campaign  | Description                                                                                                                                                                                                                                                                                                                                                                                               | Certification Level Requirements |        |        |                       | Special Courses | Additional Requirements                                                    |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|--------|--------|-----------------------|-----------------|----------------------------------------------------------------------------|
|                                    |                                                                                                                                                                                                                                                                                                                                                                                                           | Certified                        | Senior | Master | Diagnostic Specialist |                 |                                                                            |
| Safety Recall GLG/GLH/HLA          | Certain 2006 - 2012 MY IS 250/350, 2008 - 2012 MY IS F, 2007-2009 ES 350                                                                                                                                                                                                                                                                                                                                  | ✓                                | ✓      |        | ✓                     | LSC15A & LSC13B | *36 months Lexus experience and L652 + LSC13B                              |
| Limited Service Campaign (LSC) GLM | Certain 2015 RC350/RC-F & Certain 2014-2015 IS 250/350 Rear Wheel Arch Corrosion                                                                                                                                                                                                                                                                                                                          |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall GLB                  | 2004-2006 GX 470 & 2003-2006 LX 470 SRS ECU                                                                                                                                                                                                                                                                                                                                                               |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Special Service Campaign (SSC) GLP | Certain 2015-2017 MY NX 200t & NX 300h ABS Software Update                                                                                                                                                                                                                                                                                                                                                | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Limited Service Campaign (LSC) GLL | Certain 2016 MY RX 350 & RX 450h Power Rear Hatch ECU                                                                                                                                                                                                                                                                                                                                                     | ✓                                | ✓      | ✓      | ✓                     |                 |                                                                            |
| Safety Recall GLJ                  | 2011-2012 MY CT 200h Curtain Shield Airbag                                                                                                                                                                                                                                                                                                                                                                |                                  |        | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall GLK                  | Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1                                                                                                                                                                                                                                                                                                        |                                  | ✓      | ✓      | ✓                     | LSC15A & LSC13C | L453                                                                       |
| Limited Service Campaign (LSC) GLI | Certain 2016 MY RC 300 AWD & RC 350 AWD Carpet Floor Mat Replacement                                                                                                                                                                                                                                                                                                                                      | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Special Service Campaign (SSC) GLE | Certain 2016 MY RX 450h Fuel Tank Ring Replacement                                                                                                                                                                                                                                                                                                                                                        |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Limited Service Campaign (LSC) GLD | Certain 2015 MY GS 350, LS 460 RC 350 and certain 2016 MY GX 460, IS 200t/300/350, NX 200t Safety Connect System                                                                                                                                                                                                                                                                                          |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall GLC                  | Certain 2016 MY ES 350 & RX 350 Brake Actuator Inspection/Replacement                                                                                                                                                                                                                                                                                                                                     |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall GLA                  | Certain 2016 Model Year RX355, RX400h Driver Knee Airbag Inspection and Replacement                                                                                                                                                                                                                                                                                                                       |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Special Service Campaign (SSC) FLF | Certain 2010 - 2012 Model Year HS 250h Vehicles Fuel Pump and Wire Harness Replacement                                                                                                                                                                                                                                                                                                                    |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall FLE                  | Certain 2013 - 2015 Model Year ES350, ES300h Pre-Collision System                                                                                                                                                                                                                                                                                                                                         |                                  | ✓      | ✓      | ✓                     | LSC15A, LSCFLE  |                                                                            |
| Safety Recall FLD                  | Certain 2007 Model Year RX400h Powertrain and Hybrid ECU Software Update                                                                                                                                                                                                                                                                                                                                  | ✓                                | ✓      | ✓      | ✓                     | LSC15A          | *L623                                                                      |
| Safety Recall FLC                  | 2015 Model Year NX 200t Vehicles Brake Actuator                                                                                                                                                                                                                                                                                                                                                           |                                  | ✓      | ✓      | ✓                     | LSC15A*         | *With Self-Paced Module HL511A                                             |
| Limited Service Campaign (LSC) FLB | Certain 2010 Model Year RX450h Vehicles Oxygen Sensor Replacement                                                                                                                                                                                                                                                                                                                                         |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Limited Service Campaign (LSC) FLA | 2013 Model Year GS350 and GS450h Vehicles Front Passenger Supplemental Restraint System                                                                                                                                                                                                                                                                                                                   |                                  | ✓      | ✓      | ✓                     | LSC15A          | L652                                                                       |
| Safety Recall ELG                  | For Areas of High Absolute Humidity 2002 through 2005 Model Year SC 430 Vehicles Front Passenger Air Bag Inflator Module                                                                                                                                                                                                                                                                                  | ✓                                | ✓      | ✓      | ✓                     | LSC15A & LSC13B | *36 months Lexus experience and L652 + LSC13B                              |
| Safety Recall ELF                  | Certain 2007-2011 GS350, 2007-2011 IS350, 2010 IS350C (2GR-FE Engine), Certain 2006 GS300 (3GR-FE Engine), Certain 2006-2010 IS250, 2010 IS250C (4GR-FSE Engine), Certain 2007-2010 LS460 (1UR-FSE Engine), 2008-2011 LS600h (2UR-FSE Engine), Certain 2008-2011 GS460 (1UR-FSE Engine), Certain 2007-2011 GS450h (2GR-FSE Engine), Certain 2008-2011 IS-F (2UR-GSE) Vehicles Fuel Pressure Sensor Gasket | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Limited Service Campaign (LSC) ELE | Certain 2008 through 2012 Model Year IS F Vehicles Engine Cooling Fans                                                                                                                                                                                                                                                                                                                                    |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall ELD                  | Certain 2015 MY RX 350 Vehicles Equipped with 2GR-FE Engine Potential Fuel Delivery Pipe Leak                                                                                                                                                                                                                                                                                                             | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall ELB                  | 2013 GS 350 Vehicles Brake Pedal Load Sensing Switch                                                                                                                                                                                                                                                                                                                                                      |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall ELA                  | 2012-2013 RX350 Brake Actuator Reprogramming                                                                                                                                                                                                                                                                                                                                                              | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall DSC                  | 2002-2004 SC430 Vehicles Front Passenger Air Bag Inflator Module                                                                                                                                                                                                                                                                                                                                          | ✓                                | ✓      | ✓      | ✓                     | LSC15A & LSC13B | *36 months Lexus experience and L652 + LSC13B                              |
| Safety Recall DLG                  | 2006-2011 IS350, 2010-2011 IS350C, 2007-2011 GS350 2GR-FSE Intake VVT Actuator Gear                                                                                                                                                                                                                                                                                                                       |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Safety Recall DLF                  | 2006-2008 RX400h Intelligent Power Module (IPM) Replacement                                                                                                                                                                                                                                                                                                                                               |                                  | ✓      | ✓      | ✓                     | LSC15A          | L071                                                                       |
| Safety Recall DLD                  | 2010 Model Year HS250h Vehicles Brake Booster Pump Assembly (Accumulator)                                                                                                                                                                                                                                                                                                                                 |                                  | ✓      | ✓      | ✓                     | LSC15A          | *It up to the Dealer's discretion as to which technicians can perform this |
| Safety Recall DLC                  | 2002-2003 SC430 Front Passenger Airbag Inflator Module                                                                                                                                                                                                                                                                                                                                                    | ✓                                | ✓      | ✓      | ✓                     | LSC15A & LSC13B | *36 months Lexus experience and L652 + LSC13B                              |
| Safety Recall CSE                  | Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1                                                                                                                                                                                                                                                                                                        |                                  | ✓      | ✓      | ✓                     | LSC15A & LSC13C | L453                                                                       |
| SSC BSL                            | 2010 RX350, 2008 - 2010 LX570 Smart Stop Technology                                                                                                                                                                                                                                                                                                                                                       | ✓                                | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |
| Limited Service Campaign (LSC) 9LH | 9LH Extension; 2007-2009 RX 350 and 2007-2008 ES 350 Vehicles 2GR-FE (V6) Engine VVT-i Oil Hose Replacement                                                                                                                                                                                                                                                                                               |                                  | ✓      | ✓      | ✓                     | LSC15A          |                                                                            |