

Subject

**HV Battery Cooling System Low Performance  
"Warning Message"**

Market

USA

Service Category

Engine/Hybrid System

Section

Hybrid/Battery Control System

Applicability

Prius

**APPLICABLE VEHICLES**

2013-2014

Prius

**CONDITION**

Drivers of 2013, 2014 Prius vehicles may notice a warning message appear in the multi information display. The warning pertains to diminished performance of the HV Battery Cooling system, possibly due to air flow restriction.

COOLING PERFORMANCE  
OF THE HYBRID  
BATTERY IS LOW  
CONSULT A DEALER

**RECOMMENDATIONS**

- Check for obstructions to the air inlet area (to the right of the rear seat)
- Check HV Battery Cooling System Fan for dust and debris accumulation.
- Refer to T-SB-0198-11 for more information regarding cleaning and maintaining the HV Battery Cooling system



**LINK REFERENCES**

1. [T-SB-0198-11: '10-'12 Prius: HV Battery Cooling Fan Maintenance for Severe Usage Vehicles](#)