

Tech Tip T-TT-0246-13

July 25, 2013

Subject

Window and Windshield Product Report Tips

USA

Vehicle Exterior

Multiple Models

Window/Glass

APPLICABLE VEHICLES

	The second secon			
2009-2014	Highlander	2009-2014	FJ Cruiser	
2009-2014	Camry	2009-2014	Prius	
2009-2014	Tundra	2009-2014	Sienna	
2009-2014	Matrix	2013-2014	Avalon HV	
2012-2014	RAV4 EV	2012-2014	Prius V	
2009-2011, 2013-	Land Cruiser	2009-2014	4Runner	
2014				
2009-2014	Sequoia	2009-2014	Avalon	
2009-2014	RAV4	2009-2014	Venza	
2010, 2012-2014	Prius PHV	2009-2014	Yaris	
2009-2014	Tacoma	2012-2014	Prius C	
2009-2014	Highlander HV	2009-2014	Corolla	
2009-2014	Camry HV			

CONDITION

Tips for writing a DPR (Dealer Product Report) on manufacturing issues for windows and windshields.

RECOMMENDATIONS

If you encounter a vehicle that exhibits a manufacturing issue and you're planning to submit a DPR on the issue; please include a photo that outlines the concern area with white paint marker and a photo of the Regulation ID which is located in the lower corner of the glass.

<u>NOTE</u>: Do <u>NOT</u> write reports on stone chips or other outside influences that cause glass damage.

Before taking a picture of the Regulation ID, place a blank sheet of paper behind the Regulation ID (sheet of paper must create a contrast with the text of the Regulation ID).



LINK REFERENCES

This Tech Tip does not contain any link references

Expires on

07/25/2014

© 2013, Toyota Motor Sales, USA

Page 1 of 2



July 25, 2013

Window and Windshield Product Report Tips

USA

Multiple Models

07/25/2014

© 2013, Toyota Motor Sales, USA

Page 2 of 2

Ver. 2.1 8/28/2011 T