

Product Quality and Service Support, Quality Compliance Published October 5, 2017 Approved By: Tom Trisdale, General Manager – Field Action & Liason Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive Plano, TX 75024 (469) 292-4000

To: All Toyota Dealers

From: Product Support Division

Special Service Campaign H0P – Remedy Notice Certain 2017 Model Year Yaris Vehicles Instrument Panel Wire Harness

Special Service Campaign H0P Dealer Letter and Technical Instructions are now available on TIS.

Refer to the Dealer Letter and Technical Instructions on TIS for additional information.

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.