

Subject		Market
Warranty Replacement of Non-OEM Headlamps		USA
Service Category	Section	
Vehicle Exterior	Lighting (ext)	
Applicability		
2013-2015 RX350		

APPLICABLE VEHICLES

2013-2015	RX350
-----------	-------

CONDITION

Some vehicles with aftermarket headlamps (non OEM) are being repaired/replaced under warranty with OEM equipment.

RECOMMENDATIONS

When investigating customer complaints related to Headlamp issues (e.g. inoperative, intermittent function, open circuit, water entry, etc.), please verify that the Headlamp assembly is an OEM (not aftermarket) component.

OEM components can be identified by the presence of the markings shown below. Parts without these markings should be considered aftermarket components and not subject to Warranty replacement.

**OEM Headlamp Identification Markings
(P/N: 81110 and 81150)**

"NAL" lettering on the front lens.



"TOYOTA" lettering on the back side

LINK REFERENCES

This Tech Tip does not contain any link references