



Warranty Communication

Audi Warranty

Number: AWC-18-04

Subject: Fuel tank refill for vehicles receiving the TDI emissions modification

Date: Jan 31, 2018

Dealers: U.S., Puerto Rico

This document conveys general Warranty information.

This communication is to remind dealers that any customer-owned vehicles on which the TDI emissions modification is performed should be returned to the customer with a full tank of fuel after the emissions modification is performed.

The fuel tank refill is mandatory, and dealers will be reimbursed for the full cost of the refill. The fuel tank refill was provided for in the booklet that was sent to customers in connection with the TDI settlement.

Warranty coding for the fuel tank refill can be found in the following “Customer Delight” coding documents, which are available on Audi Warranty Online:

- AWA 17-13 for Gen 2.1 3.0L vehicles
- AWA 18-02 for Gen 2 PC 3.0L vehicles

Questions or concerns may be directed to Audi Warranty at 866.677.2834 or AudiWarranty@audi.com.