

Subject

**Unintended Airbag Deployment or Other SRS Performance Concerns**

Market

USA

Service Category

Vehicle Interior

Section

Supplemental Restraint Systems

Applicability

All Scion vehicles equipped w/airbags

**APPLICABLE VEHICLES**

2008-2013	xD	2013	iQ EV
2013	FR-S	2004-2006, 2008-2013	xB
2005-2013	tC	2004-2006	xA
2012-2013	iQ		

**CONDITION**

Scion vehicles are equipped with Supplemental Restraint Systems (SRS), including various airbags and in some models, seat belt pre-tensioners, to help reduce the risk of injury in a collision. If a customer expresses any concerns that the SRS airbags or pre-tensioner devices did not perform as expected (including an unintended deployment event), please follow the steps in the recommendations section below.

**RECOMMENDATIONS**

1. Open a Repair Order for any vehicle with an SRS performance concern.
2. Record specific details from the customer on the operating conditions when the concern occurred in the Repair Order.
3. Perform a Techstream HealthCheck and record any stored Diagnostic Trouble Codes.
4. Open a Technical Assistance case (TAS) with all relevant details and call for diagnostic support.

**LINK REFERENCES**

This Tech Tip does not contain any link references.