

From: [Quality Compliance](#)
Subject: Special Service Campaign G0G - Certain 2015 – 2016 Model Year Sienna Vehicles - Oxygen Sensor Replacement (Internal)
Date: Monday, June 13, 2016 5:49:04 PM
Attachments: [G0G - RL - Rem - Approved \(CARB Approved\).pdf](#)
[G0G - TIS Package.pdf](#)
[G0G TI Sienna Rem Final 061316.pdf](#)

In our continuing efforts to ensure the best in customer satisfaction, Toyota is launching a Special Service Campaign (SSC) on certain 2015 - 2016 Model Year Sienna Vehicles.

Condition

The subject vehicles are equipped with an Oxygen Sensor which could experience wire degradation inside the Oxygen Sensor wiring harness caused by vehicle vibration during normal operation. If this occurs, the vehicle will illuminate the check engine light.

Remedy

Authorized Toyota dealerships are requested to replace the Oxygen Sensor at **no charge** to the vehicle's owner.

Covered Vehicles

There are approximately 24,100 certain 2015 – 2016 Model Year Sienna vehicles covered by this Special Service Campaign.

Model Name	Model Year	Production Period
Sienna	Certain 2015 –2016	Early January, 2015 through Late December, 2015

Dealer Notification

- Dealers will be notified electronically on Tuesday 6/14/2016 at approximately 6 p.m. PST
- Claim filing will be available starting 6/15/2016

Please reference the attached Dealer Letter for additional details.

Thank you for your cooperation.

Quality Compliance Department
Toyota Motor Sales, U.S.A., Inc.
Tel. 310-468-5516
Fax 310-381-8095



We are unified in our passion
to provide the finest ownership experience.



NOTICE: This email message and all attachments transmitted with it are intended solely for the use of the addressee and may contain legally privileged and confidential information. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, copying, or other use of this message or its attachments is strictly prohibited.

If you have received this message in error, please notify the sender immediately by email reply and please delete this message from your computer. Thank you.