

Lonnie Peterson / TMS Toyota Customer Services  
Product Quality and Service Support, Quality Compliance  
July 10, 2015  
Approved By: Tom Trisdale

To: All Toyota Dealers  
From: Product Support Division

**Warranty Enhancement Program – ZE7**  
**\*\*\*\*\*Part Kit Information Update for RAV4 Vehicles\*\*\*\*\***

Currently the Repair Kit for RAV4 Vehicles PN: 04004-11828 is missing exhaust gasket 90917-06078 which is required for vehicle repair. Dealerships should order the service part number 90917-06078 at this time to supplement this kit contents. The warranty system has been modified to accept this additional required part.

Additionally the current RAV4 kits contain a gasket that is not required for the repair; dealerships should discard exhaust gasket part number 17451-31010.

We will notify dealerships again when the kit contents have been corrected and this action is no longer necessary.

Thank you for your support