

Wind deflector net loose

Topic number	LI77.21-P-055302
Version	1
Design group	77.21 Panoramic roof
Date	02-04-2013
Validity	Model series 166 with panoramic roof (code 413)
Reason for change	
Reason for block	

Complaint:

Wind deflector net loose.

Cause:

1. Profile rail (2) in PU channel in trim (1) may be incorrectly installed (automatically ribbed by the supplier since 01/12).
2. PU channel in trim (1), gap too large.
2. PU channel in trim (1), material can expand in the heat, the gap becomes larger and the profile rail (2) can loosen due to the tension of the net.
3. The profile rail (2) may have "barbs" on one side only (should be on both sides).

Remedy:

Do not replace the wind deflector with net (3), but insert the profile rail (2) into the PU channel (1) by gluing the profile rail (2) on the left and right outside.

Use commercially available instant adhesive Loctite 495.

Clean Point: The profile rail is glued in series production (supplier) since 07/12.

Attachments	
File	Designation
Bild BR166 ASD WAW Netz lose.jpg	Picture of model series 166 glass top sliding roof wind deflector net loose

Symptoms
Body / Roof system / Panoramic sunroof / Deformed

Work units				
Op. no.	Operation text	Time	Damage code	Note
			78129 IA	Deformed

Validity

Vehicle	Engine	Transmission
GL (166)	*	*
M (166)	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
166.003	651.960	722.908
166.004	651.960	722.908
166.023	642.826	722.903
166.023	642.826	725.031
166.024	642.826	722.903
166.024	642.826	725.031
166.055	276.955	722.906
166.057	276.955	722.906
166.058	276.955	722.906
166.073	278.928	722.909
166.073	278.928	725.031
166.073	278.928	725.032
166.074	157.982	722.905
166.074	157.982	722.931
166.823	642.826	722.903
166.823	642.826	725.031
166.824	642.826	722.903
166.824	642.826	725.031
166.872	278.928	722.909
166.872	278.928	725.031
166.872	278.928	725.032
166.873	278.928	722.909
166.873	278.928	725.031
166.873	278.928	725.032
166.874	157.982	722.905
166.874	157.982	722.931

Attachments

Bild BR166 ASD WAW
Netz lose.jpg:

BR 166 ASD Windabweiser Netz lose

