Crackling and cracking noises when cornering

Topic number LI40.10-P-059248

Version 1

Design group 40.10 Wheels, tires

Date 06-23-2014

Validity Model 204.#77 with code 785 or 793 (AMG light alloy

wheel with cross-spoke design)

Reason for change Reason for block

Complaint:

Crackling and cracking noise from the outer wheel on the front axle when cornering.

Cause:

Under analysis

Remedy:

Please report vehicles with this problem to AMG-Germany through your local market support department via PTSS.

Please attach the following information to the PTSS case:

- Sound file (a video is best)
- Photos of the contact points (on brake disk and wheel) with the wheels removed (see attachment for example photos)

Note:

Replacing parts (e.g. wheel bearings) does not adress the complaint. MBUSA will advise on a remedy via PTSS case-by-case and will update LI document accordingly. Please be cognizant there will be a slight delay in response time due to communication in different time zone (AMG-Germany).

Attachments		
File	Description	
Folie1.JPG	Example photo of contact point on brake disk	
Folie2.JPG	Example photo of contact point on wheel	

Symptoms	
Chassis/suspension / Chassis, noises / Cracking	
Chassis/suspension / Chassis, noises / Clattering	
Chassis/suspension / Wheels/tires / Tire noises / Rhythmic knocking	
Chassis/suspension / Wheels/tires / Rim / Current problems	
Chassis/suspension / Chassis, noises / Creaking	

XENTRY

WIS-References			
Document number	Title	Note	Allocation
SI00.00-P-0086A	Service Information: Guide- lines for queries relating to technical complaints		Remedy

Validity				
Vehicle	Engine	Transmission		
204.077	*	*		
204.277	*	*		
204.377	*	*		