

SSM 47076	2011 Fiesta vehicles may display a DTC of U2101 after replacing an RFA module. The DTC U2101 will not cause any vehicle symptoms and can be disregarded. The RFA is not programmable and does not require programmable module installation, as-built configuration or module reprogramming when replaced.
--------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------