

SSM
47139

Some 2018 Transit vehicles with a 3.2L engine built on or after 01-Jan-2018 may exhibit various starting or drivability issues along with various diagnostic trouble codes (DTCs). Before performing any diagnostic routines, as part of the standard visual checks, inspect the powertrain control module (PCM) connectors C1232B and C1232T to ensure they are fully seated, latched, and secured.