



# Preliminary Information

## PIT3219E DRLs or Auto Headlights Will Not Disable with Headlamp Switch

### Models

| Brand:    | Model:    | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|-----------|--------------|------|-----|---------|----------------|
|           |           |              | from | to  |         |                |
| Cadillac  | Escalade  | 2003 - 2018  | All  | All | All     | All            |
| Chevrolet | Avalanche | 2003 - 2013  | All  | All | All     | All            |
| Chevrolet | Silverado | 2003 - 2018  | All  | All | All     | All            |
| Chevrolet | Suburban  | 2003 - 2018  | All  | All | All     | All            |
| Chevrolet | Tahoe     | 2003 - 2018  | All  | All | All     | All            |
| GMC       | Sierra    | 2003 - 2018  | All  | All | All     | All            |
| GMC       | Yukon     | 2003 - 2018  | All  | All | All     | All            |

### Supersession Statement

This PI was superseded to update model years and condition. Please discard PIT3219D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

Some customer may state that the Daytime Running Lamps (DRL's) or the auto headlamps will not shut off when using the daytime running lamp disable switch (Which is part of the headlamp switch). Vehicles that were built for Canada (RPO Z49) have different software that doesn't allow the DRL's or Auto headlamp to be shut off. Canada law prohibits disabling daytime running lamps (DRL's) or auto headlamps.

### Recommendations / Instructions

This is a normal operation of the vehicle and no repairs should be attempted. Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

