

Classification:

Reference:

 COPYRIGHT © NISSAN NORTH AMERICA, INC.  
 Date:

EL18-013

ITB18-016

April 12, 2018

## 2019 QX50; BATTERY TESTING WITH DSS-5000 VIN BARCODE WILL NOT SCAN

**APPLIED VEHICLES:** 2019 QX50 (J55)


### SERVICE INFORMATION

When testing the battery on an early production 2019 QX50 with the DSS-5000, the VIN barcode may not scan into the battery information screen.

If this should occur, use the [Edit Battery Information](#) screen to manually enter each field.

Make sure to use the following values:

- Battery Type: Enhanced Flooded
- Battery Rating: 720



Edit Battery Information		12.65V	Bluetooth	Wi-Fi	93%	Battery
VIN	<input type="text"/>	Battery Application	<input type="text"/>			
Vehicle Year	<input type="text"/>	Battery Post	<input type="text"/>			
Vehicle Make	<input type="text"/>	Test Location	<input type="text"/>			
Vehicle Model	<input type="text"/>	Battery Type	Enhanced Flooded			
Vehicle Technology	<input type="text"/>	Battery Rating Units	<input type="text"/>			
Battery Installation	<input type="text"/>	Battery Rating	720			

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.