

9002254 02/13/2013 MY08-10 RT

GPOP - Issue Review System

Part Number: 04766312A\$, 04766313A\$, 04862307A\$, 04766311A\$

Part Description: Power Steering Return Line

Issue Description: Some customers, in extreme cold weather climates (beyond -40 deg C), may report a leaking power steering return line. Prior to making any repairs to the vehicle, please refer to TSB 19-002-11 for the proper diagnosis and repair procedures.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system
