

9002844 02/13/2013 MY08-10 RT

GPOP - Issue Review System

Part Number: 04894772A\$, 04894773A\$, 04894756A\$, 04894757A\$

Part Description: Quarter Panel and Tail Lamp Extension

Issue Description: If the rear quarter panels and taillamp extentions have been replaced and the taillamps will not fit into the provided holes, you must modify the panel to add the lower grommet hole for 2008 – 2010 vehicles. The technician needs to measure 10 inches down from the upper hole to create the lower grommet hole. Once the new gromment hole has been added the dealer will need to tape over the now middle unused hole.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.