


TOYOTA

PRODUCT SUPPORT DIVISION

INTEROFFICE MEMORANDUM

Published: May 18, 2016

To: All Toyota Region General Managers / Vice Presidents

From: Bob Waltz 
Group Vice-President, Product Quality and Service Support

Subject: Limited Service Campaign G0K (**Remedy Notice**)
2016 Model Year Scion iA Vehicles
Inspection and Adjustment of Coolant Concentration

Specific information for Region support is provided below.

Condition

The subject vehicles may have been filled with an improper concentration of coolant and water. Under high load driving conditions this could cause the high engine coolant temperature warning light to flash or illuminate and the engine to overheat.

Dealer Notification

The attached dealer letter will be sent to all Toyota dealers on May 19, 2016.

Please reference the attached Dealer Letter for additional details.

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.

