

WJ32 - Filling in Window Cleaning Fluid (Workshop Campaign)

Model Line: **718 Boxster (982)/718 Cayman (982)
911 Carrera (991)
Panamera (971)
Macan (95B)**

Model Year: **2018**

Subject: **Window cleaning fluid**

Information: **The affected vehicles were not filled with window cleaning fluid at the factory because the window cleaning fluid is not currently available.**
For this reason, the washer fluid reservoir on the affected vehicles was only partly filled with water.

Remedial Action: **Before vehicle delivery** to customers, the washer fluid reservoir must be filled with a window cleaning fluid listed in the EPA Inventory **during the sales check**.

Affected Vehicles: Only the vehicles assigned to the campaign (see PIWIS Vehicle Information). This campaign affects 2,335 vehicles in North America.

Materials:



Information

Only use window cleaning fluid that is available on the local market and do not use window cleaning fluid with a Porsche part number until further notice.

The window cleaner concentrates must meet the following requirements:

- Dilutability 1:100
- Phosphate-free
- Suitable for plastic headlights

Materials required (locally sourced):

Part No.	Designation	Qty.
...	Window cleaner concentrate	1 ea. *

* For warranty invoicing, enter the Part No. WJ320000001, "expendable items" designation, as an **additional component** costing \$0.15 USD.

Work Procedure: 1 Fill the washer fluid reservoir with window cleaning agent with the mixture ratio 1:100.

- Mixture ratio 1:100 = 1 part window cleaner concentrate to 100 parts water (for summer filling) or 100 parts water/antifreeze mix (for winter filling).

The washer fluid reservoir was pre-filled with 2 liters of water. Depending on vehicle type and equipment, the following quantities of window cleaner concentrate are therefore required:

Vehicle type	Maximum filling capacity of washer fluid reservoir:	Required window cleaner concentrate
718 Boxster/Cayman (982)	5 liters	approx. 50 ml
911 Carrera (991)	5 liters	approx. 50 ml
Panamera (971)	6 liters	approx. 60 ml
Macan (95B)	6 liters	approx. 60 ml

Scope: **Filling washer fluid reservoir with window cleaning fluid**

Working time:

Filling washer fluid reservoir with window cleaning fluid

Labor time: **10 TU**

Materials required:

... Window cleaner concentrate As much as required*
(max. approx. 60 ml required per vehicle)

* For warranty invoicing, enter the Part No. WJ320000001, "expendable items" designation, as an **additional component** costing \$0.15 USD.

⇒ **Damage Code WJ32 066 000 1**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2018 Porsche Cars North America, Inc.