

F-PACE
XE
XF
16-18MY

A Customer may report a noise or low air flow from the HVAC system

The pollen filter has been found to be prematurely restricted causing low air flow or a noise from the HVAC system with the blower on. If a restriction is found with the filter. Please submit an EPQR detailing if the filter was recently replaced and if the filter is a pollen filter or a combi filter. Hold the part for a PRR.

Under
Investigation