

**Classification:**

AT13-019c

**Reference:**

ITB13-035c

**Date:**

August 15, 2018

## CVT FLUID LEVEL CHECK SERVICE INFORMATION

This bulletin has been amended. The APPLIED VEHICLES and SERVICE INFORMATION sections have been revised. No other changes have been made. Please discard all previous versions of this bulletin.

**APPLIED VEHICLES:**

2013 JX35 (L50)  
 2014-2019 QX60 (L50)  
 2014-2017 QX60 Hybrid (L50)  
 2019 QX50 (J55)


**APPLIED VIN and DATE:**

2013 JX35 built **AFTER** 5N1AL0M(\* \*)DC 343902 and March 26, 2013  
 2014-2019 QX60 All  
 2014-2017 QX60 Hybrid All  
 2019 QX50 All

**SERVICE INFORMATION**

Applied vehicles equipped with a CVT have a "cap" that appears to be a fluid level gauge. This "cap" will NOT have a gauge or "dipstick". This is normal. Do NOT replace the "cap" because it is thought to have a "dipstick".

Whenever checking, filling, or topping off a CVT's fluid level of an applied vehicle for any reason, use the procedure outlined in the appropriate section of the ESM.



Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.