

**On-car analysis list from October 27th, 2016
please contact VW Helpline before attempting repair**

| | Models | MY | Engine | Transmission | Topic | Customer Complaint |
|-------------------|---------------------------|-----------|------------------|---------------------|-------------------------------------|---|
| Powertrain | Tiguan | 15 | All | All | MIL-on P013E | MIL-on fault P013E in the ECM |
| | Golf R | 16 | All | All | Turbo Failure/MIL-on Misfire Faults | Customer states noise from the engine/turbo and/or MIL-on and misfire faults |
| | Golf/GTI, Golf Sportwagen | 15-17 | All | All | Fuel Level Sensor (10/11/2016) | Fuel gauge not reading full after topping up the fuel (untouched vehicles) (MUST have any of P0461/2/3 and/or B103E1A/B in ECM or Instrument cluster) |
| | Tiguan, EOS, CC | 16-17 | All | All | Rear Main Seal Leak | Customer states oil leak (untouched vehicles) |
| | Passat | 14-17 | 1.8T (CPKA/CPRA) | All | MIL-on P2407 | MIL-on fault P2407 in the ECM (untouched vehicles) |
| | Tiguan, CC | 2017 | 2.0T (CCTA/CBFA) | All | MIL-on P0016 | MIL-on fault P0016 in the ECM |
| | Golf/GTI, Golf Sportwagen | 16-17 | All | All | Fuel Line Noise | Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333) |
| Chassis | GTI | 16 | All | Standard | Clutch Pedal Noise | Clutch pedal squeal/squeak when operating clutch pedal |
| | Passat | 15-16 | All | All | Center Cap | Center cap missing after PDI (more than 100 miles on the vehicle) |
| Body | Passat | 16 | All | All | Instrument Panel Noise | Instrument panel noise (untouched vehicles after VIN HC011431) |
| | Passat | 16-17 | All | All | Parking Sensor | Parking Sensor Loose or Missing from Front/Rear Bumper |
| | Passat | 16-17 | All | All | Door Noise | Door(s) noise (untouched vehicles after VIN GC052150) |