## Next Unread Message

# **View Message**

Tront oil	0 01 01 111	00000							
							_		
Sent on	09	17	2018	Expires on 09	28	2018			
_		J				J			
From	Parts and Service Division								
Cubinat									
Subject	Request for Visit: 2016-2018 Pilot 2nd Row Seats False Latching								

### PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group

RE: Request for Visit: 2016-2018 Pilot 2nd Row Seats False Latching

This message is solely directed to Honda dealership personnel; please handle accordingly. Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

### **Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2016-2018 Pilots with a customer complaint of the 2nd row seats false latching. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

### Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

- 1. Trim must be EX-L, Touring or Elite.
- 2. No previous repair to the 2nd row seats.

### **Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.