



Technical Service Department Technical Service Operations

TECHNICAL INFORMATION

Bulletin #	Date	Page
MAS001643	05/09/2018	1/2


MODEL: Maserati Levante MY17

SUBJECT: Note on the hydraulic steering rack replacement

DESCRIPTION

In case of hydraulic steering rack replacement on Maserati Levante MY17 vehicles, in order to avoid future noise phenomenon, it is mandatory to follow the steps hereby reported (see Technical Documentation for the complete replacement procedure):

- Blow the highlighted area with compressed air
- Clean it with specific products such as heptane (or other similar products, for use permitted by current environmental protection regulations)
- Apply a protective waxy such as “Tectyl 4D750” or “Efcoat 964” (About thicknesses and times, follow what indicated from the supplier's data sheet)





Technical Service Department Technical Service Operations

Bulletin #	Date	Page
MAS001643	05/09/2018	2/2

We remind you that our ABMs are available for any questions or support, and we kindly ask your full cooperation in complying with the above mentioned indications.

Thank you for your attention.

Best regards.

Technical Service Operations
Luca Evangelisti