

F-TYPE

A Customer may report cracking of the micro headlamp lenses.

Engineering are currently investigating micro cracking of the headlamp lenses. Should a vehicle exhibit the concern, please submit an EPQR with pictures of the concern. Please ensure the cracking is not a result of damage, such as stone chipping.

Under Investigation

