

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop: Replace Rear Differential
Date: Friday, July 15, 2016 4:56:03 PM

Publish Date: July 15, 2016
From: Technical Service
Expiration Date: July 29, 2016

DCSnet Message
Urgent



Subject: **Delivery Stop: Replace Rear Differential**

A Delivery Stop was issued today on certain M2 Coupe, M3 Sedan, M4 Coupe and Convertible, 5 Series Sedan (incl. M), 6 Series Gran Coupe, Convertible, and Coupe regarding the rear differential. Attached is Service Information bulletin M33 04 16 for more details.

At this time, a repair solution is being developed. You will be updated when additional information becomes available.

Affected vehicles can be identified under "open campaign" in DCS Warranty Vehicle Inquiry or ISPA Light with the description: STOP011633 Delivery Stop B330416 No repair available at this time.

We are aware that there is German language in the system and we have escalated this issue to be resolved. You will see vehicles displayed in the key reader with the following statement for now:

F06 F1x F8x Hinterachsgetriebe

Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the delivery stop repair has been performed. This means that centers may not legally deliver new motor vehicles to a consumer until it is fixed or use/sell replacement equipment/parts subject to a delivery stop. Note also that substantial civil penalties apply to violations of this law.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a delivery stop until the repair is completed.

Sincerely,

Technical Service

Attachments:

 [B330416\[817774e8\].pdf](#)  [B330416\[817774e8\].pdf](#)

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel

