



SI B63 04 14
Lights

January 2014
Technical Service

SUBJECT

Delay in Automatic Driving Light Switching On/Off

MODEL

E60

E61

E63

E64

E65

E66

E70

E71

E82

E84

E88

E89

E90

E91

E92

E93

F01

F02

F06

F07

F10

F12

F13

F15

F25

F30

F31

F32

With option code 521 (Rain sensor)

SITUATION

When driving out of a tunnel or exiting underground parking, the automatic driving light remains switched on for two minutes, even in daylight. The automatic driving light switching on/off can be shorter or longer when it starts to get dark.

CAUSE

The software for the switch-on threshold is lowered to protect the xenon light source.

PROCEDURE

The above situation is normal operation.

DO NOT replace any part or program the vehicle.

The sensitivity of the automatic driving light can be adjusted with ISTA/P under the Retrofit/Conversion procedure by selecting “Conversion, set automatic driving lights control to very sensitive.”

Note: The conversion may not be available for all models.

WARRANTY INFORMATION

Performing this conversion is not covered under terms of the BMW New Vehicle/SAV Limited Warranty.

[Copyright ©2014 BMW of North America, Inc.]