

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: October 3, 2018
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Urgent Dealer Notification for TSB-18-54-005
TIN NO. TIN-18-54-004

.....

AFFECTED VEHICLES: 2018 Outlander PHEV

PURPOSE

In July 2018 MMNA released **TSB-18-54-005** for 2018 PHEV to address the illumination of various warning lights accompanied by DTCs P0AA7 and P0AA8 (some other DTCs may exist also). MMNA has recently discovered that a communication problem may exist with this software update and is currently asking dealers to **refrain from performing this software update on 2018 PHEVs until further notice**. MMNA anticipates a resolution to this issue very soon.

NOTE: This issue has no impact on any recall campaigns, including SR-18-007 and SR-18-008 that were released October 2, 2018.