



Technical Tip

Topic	91-18-12TT - MIB2 Composition Color Radio – CarPlay Icon is Not Present after Unplugging iPhone
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	October 26, 2018

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

MIB2 Composition Color Radio – CarPlay Icon is Not Present after Unplugging iPhone

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Passat, Golf, GTI, eGolf, Sportwagen, Beetle, Beetle Convertible, Tiguan, Atlas, Tiguan LWB	2018-2019	All	All	All	All

Technical Background

NA.

Service

If the Apple CarPlay icon is missing from the composition color unit after plugging an iPhone, disconnect the iPhone, go into the settings menu in the radio and select reset to factory settings. Plug the iPhone back into the radio and recheck for the CarPlay icon and functionality.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2052793/1	10/26/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.