

**On-car analysis list from October 3rd, 2018**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Golf, GTI, SportWagen, Jetta, Beetle, Beetle Convertible, Passat, Tiguan LWB	16-18	1.8T & 2.0T (CPPA,CPLA,CPRA,CPKA,CXBA, CXBB,CXCA,CXCB,DGUA)	All	Oil Level Thermal Sensor	Yellow oil warning light on with any of the following faults P0196 P0198 B104129 B104135 <b>(Warning light must be solid not flashing)</b> <b>(untouched vehicles)</b>
	Golf R	17	All	All	MIL-on P0300-P0304	MIL-on with P0300-P0304 in the ECM with software level 0003 <b>(TSB 01-18-02, 2050261 must have previously been performed)</b> <b>(untouched vehicles)</b>
	Touareg, Atlas	17-18	3.6L (CGRA, CDVC)	All	Coolant Leak	Coolant leak at the coolant pump <b>(leak must be from mechanical coolant pump)</b> <b>(untouched vehicles)</b>
Body	Tiguan (LWB)	18	All	All	Sunshade Binding	Customer states the sunshade is binding <b>(untouched vehicles)</b>
	Tiguan (LWB)	18	All	All	Wind Noise	Wind noise from front door window seal area <b>(untouched vehicles)</b> <b>(ONLY front door window/seal noise)</b>
	Golf, GTI	18	All	All	Sunroof Noise	Customer states the sunroof is making noise, squeak & rattle <b>(untouched vehicles)</b>
Chassis	GTI	18	All	All	Damaged Strut Boots	Damaged strut boots at PDI <b>(must be at PDI)</b> <b>(untouched vehicles)</b>
Electrical	Passat, Atlas	17-18	All	All	Key Inoperative	Customer states remote key inoperative <b>(Cars with Kessy system ONLY)</b> <b>(MUST be under 12 month, 12,000 miles)</b>
	GTI, SportWagen	17-18	All	All	"Transmission Error" Message in MFI	"Transmission Error" Message in MFI with U0212 / U021200 stored in both the ECM and TCM. <b>(untouched vehicles)</b>
	Atlas	18	All	All	Park Distance Control	Customer states park distance control too sensitive <b>(untouched vehicles)</b>
	Passat	17-18	All	All	Rear Speaker Distortion	Customer states the rear speaker is distorted <b>(untouched vehicles)</b>