

On-car analysis list from July 26th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM (untouched vehicles)
	Passat, Beetle, Jetta, Golf/GTI, Sportwagen	15-17	1.8T & 2.0T EA888 Gen 3	All	Oil pressure light with P164D	Oil pressure light with P164D in the ECM (Must have fault in the ECM)
	Golf Sportwagen (Alltrack only)	17	All	All	MIL-on P0463 and B103E1B	MIL-on P0463 and B103E1B stored (untouched vehicles)
	Jetta	17	1.4T (CZTA)	All	Fuel Gauge	Fuel gauge drops to empty with fault B103E1B (untouched vehicles)
	Passat	17	1.8T (CPRA)	All	Fuel Gauge	Fuel gauge drops to empty with faults U042300 and B103E1B (untouched vehicles)
Chassis	Jetta	16-17	All	All	Rear Brake Concerns	Rear brake noise, dragging, excessive dust (untouched vehicles)
	Jetta	17	All	All	MIL-on P0556	MIL-on P0556 in the ECM (untouched vehicles)
	Jetta	17	All	All	Rear Wheel Speed Sensor	ABS warning light with faults VAG00290 and/or VAG00287 in the ABS module (untouched vehicles)
Body	Jetta, Beetle	16 - 17	All	All	A/C Inoperative	A/C inoperative, compressor found to be locked up (compressor has to be seized) (untouched vehicles)
	Jett, Passat	17	1.8T (CPRA) 1.4T (CZTA)	All	Noise from Dash	Customer states noise from passenger side of dash (untouched vehicles) (A/C line must be contacting right side frame rail)
Electrical	Passat, Jetta, Golf/GTI, Golf Sportwagen	17	All	All	KESY Start Concerns	Keyless faulty/Keyless defective error messages with fault(s) B117213/B117313/B117413
	Passat	17	All	All	Front Assist/ACC	MFI warning for Front Assist inoperative w/ fault code C110300 (Must have Fault Code C110300) (untouched vehicles)
	Jetta	16-17	All	All	Power Window Switch	Power window switch inoperative (untouched vehicles with chrome tip after VIN 3VW167AJ6GM306370) (untouched vehicles with black tip after VIN 3VWD67AJ9GM277105)