

<b>Reference</b>	SSM73713
<b>Models</b>	F-PACE / X761 XE / X760 XF / X260
<b>Title</b>	Squeal Noise From Front Brakes Whilst Braking (17 inch only)
<b>Category</b>	Chassis
<b>Last modified</b>	02-Oct-2018 00:00:00
<b>Symptom</b>	301000 Service Brake System

**Content** **Issue:** A customer may report a squeal noise coming from front brakes during brake application. This will usually occur whilst cold.

**Cause:** Currently under investigation.

**Action:** If a customer reports this concern then please replace the brake pads. Part number: T4N13434

**Note:** Update issued due to incorrect part number.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.