

10/14/15

MY 15 & 16 LA & LD

## **GPOP - Issue Review System**

**Part Number:** 05036750A\$

**Part Description:** Powertrain Control Module

**Issue Description:** Before replacing the Powertrain Control Module on 2015-2016 6.2L Supercharged Hellcat equipped Challengers/Chargers for a P2227 (Barometric Pressure Circuit Performance) fault, please call Nick Lynn on his cell (586) 295-0917. If no response is received within 15 minutes, please continue with repair.

~ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.