

## Anti-theft alarm system (ATA) operates without obvious cause

---

Topic number	LI80.50-P-068392
Version	1
Function group	80.50 Anti-theft alarm system (ATA), Interior motion sensor/Tow sensor
Date	07-12-2018
Validity	A238
Reason for change	Cause identified, remedy now in preparation.
Reason for block	

---

### Complaint:

Anti-theft alarm system (ATA) may operate without obvious cause

False alarm caused by: Tow-away protection sensor

### Cause:

ATA control unit may erroneously activate the alarm system. Replacing parts is not effective.

### Remedy:

A remedy is currently in preparation. A new version of this document will be published as soon as the remedy is available.

<b>Symptoms</b>
Overall vehicle / Safety and locking system / Antitheft alarm system ATA / Tow-away protection / Malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			82566 EG	