

Winter tire speed limit is activated automatically

Topic number	LI54.30-P-068427
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	07-19-2018
Validity	E63 AMG BR 213
Reason for change	
Reason for block	

Complaint:

Display in instrument cluster at 235 km/h (146mph) "Speed limit (winter tires) 240 km/h"

Speed is limited to 240 km/h (146 mph)

Cause:

Lack of communication between ESP control unit and COMAND at system start.

Remedy:

Updating of ESP control unit and COMAND control unit with XENTRY (version 05/2018 or higher)

Note:

Only one control unit may also be affected by the update.

Symptoms
Communication/information / Assistance and warning systems / Distronic / Display message / Function error
Communication/information / Assistance and warning systems / Distronic / Function / Implausible regulation
Communication/information / Assistance and warning systems / Speed Limit Assist / Warning message in instrument cluster