



Safety Recall and Service Campaign - Technician Certification Requirements

Posted 12/15/2016

IMPORTANT:

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right. Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

Safety Recall or Service Campaign	Description	Certification Level Requirements				Special Courses	Additional Requirements
		Certified	Senior	Master	Diagnostic Specialist		
Limited Service Campaign (LSC) GLL	Certain 2016 MY RX 350 & RX 450h Power Rear Hatch ECU	✓	✓	✓	✓		
Safety Recall GLB	Certain 2004-2006 MY GX470 and 2003-2006 MY LX470		✓	✓	✓	L453, L652, and LSC13A	
Safety Recall GLJ	2011-2012 MY Curtain Shield Airbag			✓	✓	LSC15A	
Safety Recall GLK	Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1		✓	✓	✓	LSC15A & LSC13C	L453
Limited Service Campaign (LSC) GLI	Certain 2016 MY RC 300 AWD & RC 350 AWD Carpet Floor Mat Replacement	✓	✓	✓	✓		
Special Service Campaign (SSC) GLE	Certain 2016 MY RX 450h Fuel Tank Ring Replacement		✓	✓	✓	LSC15A	
Limited Service Campaign (LSC) GLD	Certain 2015 MY GS 350, LS 460 RC 350 and certain 2016 MY GX 460, IS 200t/300/350, NX 200t Safety Connect System		✓	✓	✓	LSC15A	
Safety Recall GLC	Certain 2016 MY ES 350 & RX 350 Brake Actuator Inspection/Replacement		✓	✓	✓	LSC15A	
Safety Recall GLA	Certain 2016 Model Year RX355, RX400h Driver Knee Airbag Inspection and Replacement		✓	✓	✓	LSC15A	
Special Service Campaign (SSC) FLF	Certain 2010 – 2012 Model Year HS 250h Vehicles Fuel Pump and Wire Harness Replacement		✓	✓	✓	LSC15A	
Safety Recall FLE	Certain 2013 – 2015 Model Year ES350, ES300h Pre-Collision System		✓	✓	✓	LSC15A, LSCFLE	
Safety Recall FLD	Certain 2007 Model Year RX400h Powertrain and Hybrid ECU Software Update	✓*	✓	✓	✓	LSC15A	*L623
Safety Recall FLC	2015 Model Year NX 200t Vehicles Brake Actuator		✓*	✓*	✓*	LSC15A*	*With Self-Paced Module HL511A
Limited Service Campaign (LSC) FLB	Certain 2010 Model Year RX450h Vehicles Oxygen Sensor Replacement		✓	✓	✓	LSC15A	
Limited Service Campaign (LSC) FLA	2013 Model Year GS350 and GS450h Vehicles Front Passenger Supplemental Restraint System		✓	✓	✓	LSC15A	L652
Safety Recall ELG	For Areas of High Absolute Humidity 2002 through 2005 Model Year SC 430 Vehicles Front Passenger Air Bag Inflator Module	✓*	✓*	✓	✓	LSC15A & LSC13B	*36 months Lexus experience and L652 + LSC13B
Safety Recall ELF	Certain 2007-2011 GS350, 2007-2011 IS350, 2010 IS350C (2GR-FE Engine), Certain 2006 GS300 (3GR-FE Engine), Certain 2006-2010 IS250, 2010 IS250C (4GR-FSE Engine), Certain 2007-2010 LS460 (1UR-FSE Engine), 2008-2011 LS600hl (2UR-FSE Engine), Certain 2008-2011 GS460 (1UR-FSE Engine), Certain 2007-2011 GS450h (2GR-FSE Engine), Certain 2008-2011 IS-F (2UR-GSE) Vehicles Fuel Pressure Sensor Gasket	✓	✓	✓	✓	LSC15A	
Limited Service Campaign (LSC) ELE	Certain 2008 through 2012 Model Year IS F Vehicles Engine Cooling Fans		✓	✓	✓	LSC15A	
Safety Recall ELD	Certain 2015 MY RX 350 Vehicles Equipped with 2GR-FE Engine Potential Fuel Delivery Pipe Leak	✓	✓	✓	✓	LSC15A	
Safety Recall ELB	2013 GS 350 Vehicles Brake Pedal Load Sensing Switch		✓	✓	✓	LSC15A	
Safety Recall ELA	2012-2013 RX350 Brake Actuator Reprogramming	✓	✓	✓	✓	LSC15A	
Safety Recall DSC	2002-2004 SC430 Vehicles Front Passenger Air Bag Inflator Module	✓*	✓*	✓	✓	LSC15A & LSC13B	*36 months Lexus experience and L652 + LSC13B
Safety Recall DLG	2006-2011 IS350, 2010-2011 IS350C, 2007-2011 GS350 2GR-FSE Intake VVT Actuator Gear		✓	✓	✓	LSC15A	
Safety Recall DLF	2006-2008 RX400h Intelligent Power Module (IPM) Replacement		✓	✓	✓	LSC15A	L071
Safety Recall DLD	2010 Model Year HS250h Vehicles Brake Booster Pump Assembly (Accumulator)					LSC15A	*It up to the Dealer's discretion as to which technicians can perform this

Safety Recall DLC	2002-2003 SC430 Front Passenger Airbag Inflator Module	✓*	✓*	✓	✓	<i>LSC15A & LSC13B</i>	*36 months Lexus experience and L652 + LSC13B
Safety Recall CSE	Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1		✓	✓	✓	<i>LSC15A & LSC13C</i>	<i>L453</i>
SSC BSL	2010 RX350, 2008 - 2010 LX570 Smart Stop Technology	✓	✓	✓	✓	<i>LSC15A</i>	
Limited Service Campaign (LSC) 9LH	9LH Extension; 2007-2009 RX 350 and 2007-2008 ES 350 Vehicles 2GR-FE (V6) Engine VVT-i Oil Hose Replacement		✓	✓	✓	<i>LSC15A</i>	