

---

<b>Reference</b>	SSM74164
<b>Models</b>	I-PACE / X590
<b>Title</b>	X590 I-PACE Front suspension noise on Air Active derivative
<b>Category</b>	Chassis
<b>Last modified</b>	16-Nov-2018 00:00:00
<b>Symptom</b>	304000 Suspension System

---

**Content**      Issue: Jaguar I-PACE front suspension noise on Air Active derivative (Air spring and active damper) when driving over speed bumps.

Cause: Noise coming from rebound spring release on Air CVD dampers.

Action: No action required - please do not replace units with new components. Engineering Permanent Corrective Action (internal damper modification) for Service parts will be introduced in week 51.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.