

SERVICE BULLETIN

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Classification: HA18-005 Reference: ITB18-044

December 13, 2018

Date:

2019 QX50; INSPECTING FOR REFRIGERANT LEAKS

APPLIED VEHICLES: 2019 QX50 (J55)

SERVICE INFORMATION

When inspecting the Air Conditioning (A/C) system in the applied vehicle for refrigerant leaks, some of the refrigerant connections may be difficult to see.

• See Figure 1 on the next page for areas that should be inspected whenever the A/C system is inspected for refrigerant leaks.


Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

Refrigerant Connections

In addition to the areas circled in GREEN below, the areas that are highlighted/circled in RED should also be inspected whenever the A/C system is inspected for refrigerant leaks.

- To inspect areas that are highlighted/circled in RED, it may be necessary to remove the front bumper fascia and front spoiler.
- Refer to the Electronic Service Manual (ESM) for front bumper fascia and front spoiler removal; BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > EXTERIOR > REMOVAL AND INSTALLATION > FRONT BUMPER.

NOTE: If a refrigerant leak is found in the areas highlighted/circled in red, replace the Liquid Tank and Condenser Assembly.



PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Liquid Tank and Condenser Assembly	92100-5NA0A	1

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION	
December 13, 2018	ITB18-044	Original bulletin published.	