



Technical Tip

Topic	97-18-02TT - Cylinders 1,2,3 or 4 - Injector Circuit Faults P0201, P0202, P0203 or P0204
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	December 14, 2018

Condition

ATTENTION:
THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Cylinders 1, 2, 3 or 4 - Injector Circuit Faults P0201, P0202, P0203 or P0204

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Jetta, Beetle, Tiguan LWB	2018	2.0L (DDSA, DGUA)	All	All	All

Technical Background

Injector circuit fault code(s) stored in the ECM. Caused by harness connection issues.

Service

Inspect the injector harness (the short 8 pin harness), for bent or loose connections.

- Repair any concerns noted.

Inspect the injector pins for damage and verify the connector is fully seated and connector lock is engaged.

- Repair any concerns.

If there are no issues with the injector harness:

- Replace the 105 pin Engine harness. Once completed, road test and re-evaluate engine performance.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053319/1	12/14/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.