

## Transmission Control Module Updates

Model Year	Model	Engine	Complaint	Module Part #	Updated Software Level	Technical Bulletin #	CD Number	SVM Unit
1999-2002	A4 Golf Jetta	2.8L AFP	Automatic Transmission slips when shifting from 2nd to 3rd gear	01M927733MP	5060	37 07 05	Replace TCM	N/A
				01M927733DJ>01M927733MP				
				01M927733JS>01M927733MP				
				01M927733KR>01M927733MP				
				01M927733MB>01M927733MP				
				01M927733MH>01M927733MP				
2006	B6 Passat	2.0L BPY	Harsh 5-4 downshift	09G927750CJ	1135	01 09 15	N/A	300B
2004	B5 Passat	2.8L ATQ	Harsh 3-2 downshift	3B0927156BA	2225	01 07 18	W42PASS ATSHIFT	N/A
				3B0927156AT				
2007	B6 Passat, Passat Wagon	2.0L BPY	Harsh downshift after extended highway driving	09G927750FP	1119	01 09 20	N/A	300B
2006-2007	B6 Passat	2.0L BPY	Harsh shifting when cold	09G927750CJ	1135	01 07 61 and 01 07 62	PASSSW1 135	N/A
2008	A5 Jetta A5 GTI	2.0L BPY	Harsh 1-2 or 2-3 upshift	ECM: 1K0907115S	.0040.	01 09 14	N/A	317D
				TCM: 02E300044J	1416			

## Transmission Control Module Updates

Model Year	Model	Engine	Complaint	Module Part #	Updated Software Level	Technical Bulletin #	CD Number	SVM Unit
2007	A5 Jetta A5 GTI	2.0L BPY	Launch Control Program	02E325025AD	1158	37 07 09	W42DQ25 ORD2	N/A
2009	Tiguan	2.0L CCTA	Harsh 3-2 down shift when cold	09G927750GG	1702	01 09 19	N/A	.32E1.
				09G927750KM	1703			
				09G927750KN	1704			
2004- 2006-	Touareg	ALL	Transfer case binding	(All Wheel Drive Control Module) 0AD927755BE	.0122.	01 09 16	W42SWU 0122	N/A
2012	Jetta, Jetta Sportwag en, Passat, Beetle, CC, Tiguan, Golf	2.5L CBUA CBTA 2.0T CCTA 3.6L CNNA	Fault Code 00266 Stored in TCM	09G 927 750HG	2172	01 12 12	N/A	36AD
				09G 927 750JE	2169			
				09G 927 750MH	2195			
				09G 927 750LM	2178			
				09G 927 750LR	2196			
				09G 927 750LE	2174			
				09G 927 750LF	2175			
				09G 927 750LG	2176			
09G 927 750LH	2177							
2012	Tiguan	2.0L CCTA	Slight Hesitation and or Driving Noise at Low Speeds in High Gear	09G 927 750LR>09G 927 750NK	2253	01 12 13	N/A	3703
				09G 927 750LR>09G 927 750NK	2248			

## Transmission Control Module Updates

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Complaint</u>	<u>Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>CD Number</u>	<u>SVM Unit</u>
2012	Golf, Jetta, Jetta Sportwagen, Golf Wagon	2.0L CJAA	Slight Hesitation Concerns	03L 906 019EF>03L 906 019HG	2261	01 12 10	N/A	36C6
				03L 906 019EG>03L 906 019HH	2260			
				02E 300 057A>02E 300 057P	3102			
				02E 300 054J>02E 300 057P	3102			
2006-2007	Passat, Passat	2.0L BPY	Harsh Downshift after Extended Highway Driving	09G 927 750FP	1199	01 11 31	N/A	300B
			09G 927 750CJ	1135				
2007-2008	Passat, Passat Wagon, Jetta, Jetta Wagon	2.0L BPY	ECM/TCM Software Update and Valve Body Replacement for Harsh Up - Down Shift from Transmission when Cold	3C0 907 115P>3C0 907 115S	.0020.	01 11 30	N/A	320A
				3C0 907 115S	.0020.			
				09G 927 750FP>09G 927 750C	1616			
				09G 927 750HJ>09G 927 750C	1617			
				09G 927 750FL>09G 927 750D	1649			
				09G 927 750D	1649			
09G 927 750HE>09G 927 750E	1615							
2011-2012	Golf, Golf Wagon, Jetta,	2.5L CBUA CBTA CCCA	Harsh Engagement from Part to Drive or Reverse	09G 927 750LH	1916	01 11 15	N/A	3548
			09G 927 750LM	1919				
			09G 927 750LF	1914				