

**On-car analysis list from March 15th, 2019**  
**please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Jetta	19	All	All	Heat Shield	Customer states noise from heat shield <b>(untouched vehicles)</b>
	Beetle, Tiguan LWB, Passat, Jetta	18-19	All	All	MIL-on P0456	Customer states MIL-on <b>(MUST have P0456 in the ECM)</b> <b>(untouched vehicles)</b>
	Tiguan LWB	19	All	All	MIL-on P11AD, P11AE, P11AF	Customer states MIL-on <b>(Must have one or all of P11AD, P11AE, P11AF )</b> <b>(untouched vehicles)</b>
<b>Body</b>	ATLAS	18	All	All	2nd Row Seat Noise	Customer states 2nd row seat rattles while driving <b>(ONLY VEHICLES AFTER VIN JC555474)</b> <b>(untouched vehicles)</b>
	Jetta	19	All	All	Front window(s) noisy during operation	Customer states front window(s) noisy during operation <b>(untouched vehicles)</b>
	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding <b>(untouched vehicles)</b>
<b>Chassis</b>	Jetta	19	All	All	Rear Speed Sensor	Customer states MIL-on and/or multiple warning lights <b>(MUST include any of the following faults associated with the rear wheel speed sensor: C101C01, C101D01, C101C11, C101D11, C101C12, C101D12, C101C14, C101D14, C101C29, C101D29, C10E2F0)</b> <b>(untouched vehicles)</b>
	Tiguan LWB	18-19	All	All	Rear Speed Sensor	Customer states MIL-on and/or multiple warning lights <b>(MUST include any of the following faults associated with the rear wheel speed sensor: C101C01, C101D01, C101C11, C101D11, C101C12, C101D12, C101C14, C101D14, C101C29, C101D29, C10E2F0)</b> <b>(untouched vehicles)</b>
<b>Electrical</b>	Passat	19	All	All	Kessy Inoperative	Customer states Kessy inoperative possibly with "Keyless Defective" in MFI <b>(Must have at least one or more of B117213, B117313, B117413 in Kessy Module)</b> <b>(untouched vehicles)</b>