

**On-car analysis list from March 27th, 2019**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Jetta	19	All	All	Heat Shield	Customer states noise from heat shield <b>(untouched vehicles)</b>
	Beetle, Tiguan LWB, Passat, Jetta	18-19	All	All	MIL-on P0456	Customer states MIL-on <b>(MUST have P0456 in the ECM)</b> <b>(untouched vehicles)</b>
	Tiguan LWB	19	All	All	MIL-on P11AD, P11AE, P11AF	Customer states MIL-on <b>(Must have one or all of P11AD, P11AE, P11AF )</b> <b>(untouched vehicles)</b>
<b>Body</b>	Jetta	19	All	All	Front window(s) noisy during operation	Customer states front window(s) noisy during operation <b>(untouched vehicles)</b>
	Jetta	19	All	All	Headliner Noise/Loose	Customer states the headliner makes noise, is loose or hangs down <b>(untouched vehicles)</b>
	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding <b>(untouched vehicles)</b>
	Golf	16	All	All	Front Window(s) Noise or Inop	The front window regulator(s) exhibiting noise, shutter, binding, or is inoperative. <b>(untouched vehicles)</b>
	Jetta, Tiguan	18-19	All	All	A/C Pressure Sensor Faults	Customer states AC inoperative <b>(must have B10AE31 and/or B10AE04 in the HVAC Module (08))</b> or <b>(blower motor continue to run with key off)</b>
	Passat	19	All	All	Temperature Blend Door Linkage	Customer states no/low heat output <b>(Temperature blend door linkage must be loose/disconnected)</b>
	Passat	19	All	All	Drivers Seat Forward/Backwards Inop	Customer states drivers front seat does not move forwards/backwards
<b>Chassis</b>	Jetta	19	All	All	Rear Speed Sensor	Customer states MIL-on and/or multiple warning lights <b>(MUST include any of the following faults associated with the rear wheel speed sensor: C101C01, C101D01, C101C11, C101D11, C101C12, C101D12, C101C14, C101D14, C101C29, C101D29, C10E2F0)</b> <b>(untouched vehicles)</b>